



EFR32 Wireless Gecko EFR32FG23 Errata



This document contains information on the EFR32FG23 errata. The latest available revision of this device is revision B. Errata that have been resolved remain documented and can be referenced for previous revisions of this device. The device data sheet explains how to identify the chip revision, either from package marking or electronically. Errata effective date: December, 2021.

1. Errata Summary

The table below lists all known errata for the EFR32FG23 and all unresolved errata in revision B of the EFR32FG23.

Table 1.1. Errata Overview

Designator	Title/Problem	Workaround Exists	Exists on Revision:	
			A	B
CUR_E302	Extra EM1 Current if FPU is Disabled	Yes	X	X
DCDC_E302	DCDC Interrupts Block EM2/3 Entry or Cause Unexpected Wake-up	Yes	X	X
EUSART_E301	PRS Transmit Unavailable in Synchronous Secondary Mode	No	X	—
EMU_E305	DC-DC Refresh Time Delay	Yes	X	X
I2C_E303	I2C Fails to Indicate New Incoming Data	Yes	X	—
IADC_E305	FIFO Cannot Detect Eighth Entry	Yes	X	X
RADIO_E306	Improper TX and RX Operation at High Temperature	Yes	X	X
USART_E301	Possible Data Transmission on Wrong Edge in Synchronous Mode	Yes	X	—
USART_E302	Additional SCLK Pulses Can Be Generated in USART Synchronous Mode	Yes	X	—
USART_E304	PRS Transmit Unavailable in Synchronous Secondary Mode	No	X	X

2. Current Errata Descriptions

2.1 CUR_E302 – Extra EM1 Current if FPU is Disabled

Description of Errata
When the Floating Point Unit (FPU) is disabled, the on-demand Fast Startup RC Oscillator (FSRCO) remains on after an energy mode transition from EM0 to EM1 is complete. This leads to higher current consumption in EM1.
Affected Conditions / Impacts
The enabled FSRCO increases EM1 current consumption by ~500 µA.
Workaround
Always enable the FPU at the beginning of code execution via the Coprocessor Access Control Register (CPACR) in the System Control Block (SCB) as shown below:
<pre>SCB->CPACR = ((3 << 20) (3 << 22));</pre>
Resolution
There is currently no resolution for this issue.

2.2 DCDC_E302 – DCDC Interrupts Block EM2/3 Entry or Cause Unexpected Wake-up

Description of Errata
Regardless of DCDC_IEN setting, if the DCDC interrupt is enabled in the NVIC, any of the four DCDC interrupt sources (DCDC_IF_WARM, DCDC_IF_RUNNING, DCDC_IF_TMAX, and DCDC_IF_BYPSW) can wake the device from EM2/3 or prevent it from entering EM2/3.
Affected Conditions / Impacts
The errata is limited to the DCDC_IF_WARM, DCDC_IF_RUNNING, DCDC_IF_TMAX and DCDC_IF_BYPSW requests, which also function as wake-up sources from EM2/3.
When the NVIC DCDC interrupt source is enabled:
<ul style="list-style-type: none"> • If IEN for one of these interrupt requests is set to 1 and that condition occurs, then an interrupt <i>*will*</i> occur and the CPU will branch to the DCDC IRQ handler. • If IEN for one of these interrupt sources is cleared to 0 and that condition occurs, then an interrupt <i>*will not*</i> occur. • If any of these four interrupt conditions occurs, regardless of the setting of their corresponding DCDC_IEN bits, the device <i>*will*</i> wake from EM2/3 and/or be prevented from entering EM2/3. If the corresponding IEN was not set, an interrupt <i>*will not*</i> occur even though the EM2/3 wakeup event has occurred.
Workaround
To prevent unwanted wake-up from or blocked entry into EM2/3, disable the DCDC interrupt using <code>NVIC_DisableIRQ(DCDC_IRQn)</code> before entering EM2/3 and re-enable the DCDC interrupt using <code>NVIC_EnableIRQ(DCDC_IRQn)</code> after EM2/3 wake-up.
Resolution
There is currently no resolution for this issue.

2.3 EMU_E305 – DC-DC Refresh Time Delay

Description of Errata
The DC-DC fast refresh delay required after exiting EM2/3 and entering continuous conduction mode (CCM) is not honored.
Affected Conditions / Impacts
When the system exits EM2/3 and the DC-DC is set to CCM, the DC-DC voltage comparator needs to be refreshed. This refresh delay is not honored when exiting EM2/3.
Workaround
Firmware must wait for at least 20 μ s before enabling DCDC CCM upon wake from EM2/3.
Resolution
There is currently no resolution for this issue.

2.4 IADC_E305 – FIFO Cannot Detect Eighth Entry

Description of Errata
The IADC is unable to detect when the eighth FIFO entry has been loaded and will not set the corresponding SINGLEFIFODVL or SCANFIFODVL flag in the IADC_IF register or request LDMA service.
Affected Conditions / Impacts
If the DVL field of IADC_SINGLEFIFOCFG or IADC_SCANFIFOCFG is set to VALID8, a FIFO full condition is not registered when the eighth FIFO entry is loaded. In particular, this means that if the LDMA is configured to empty the FIFO when it is filled with eight entries, the LDMA will never issue a request to perform the transfers necessary to do this.
Similarly, the IADC will not set the IADC_IF_SINGLEFIFODVL or IADC_IF_SCANFIFODVL to request an interrupt in response to the FIFO being filled with eight entries.
Workaround
Do not configure the IADC to request an interrupt or LDMA service when all eight entries are full (IADC_SINGLEFIFOCFG_DVL = VALID8 or IADC_SCANFIFOCFG_DVL = VALID8). All other settings of the DVL field (VALID1 to VALID7) operate as expected.
Resolution
There is currently no resolution for this issue.

2.5 RADIO_E306 – Improper TX and RX Operation at High Temperature

Description of Errata
Some devices may fail to lock to the correct RF frequency at high operating temperatures (above 120 °C).
Affected Conditions / Impacts
Devices using Gecko SDK prior to v4.0.0 at high operating temperatures may be unable to lock to the desired RF frequency. This may cause errors in the TX/RX frequency or an inability to transmit or receive data.
Workaround
Customers should use firmware provided in Gecko SDK v4.0.0 or later for proper TX/RX operation.
Resolution
There is currently no resolution for this issue.

2.6 USART_E304 — PRS Transmit Unavailable in Synchronous Secondary Mode

Description of Errata
When the USART is configured for synchronous secondary operation, the transmit output (MISO) is not driven if the signal is routed to a pin using the PRS producer (e.g., SOURCESEL = 0x20 and SIGSEL = 0x4 for USART0).
Affected Conditions / Impacts
Systems cannot operate the USART in synchronous secondary mode if the PRS is used to route the transmit output to the RX (MISO) pin. Operation is not affected in main mode when the transmit output is routed to the TX (MOSI) pin using the PRS producer nor is operation affected in any mode when the GPIO_USARTn_RXROUTE and GPIO_USARTn_TXROUTE registers are used.
Workaround
There is currently no workaround for this issue.
Resolution
There is currently no resolution for this issue.

3. Resolved Errata Descriptions

This section contains previous errata for EFR32FG23 devices.

For errata on the latest revision, refer to the beginning of this document. The device data sheet explains how to identify chip revision, either from package marking or electronically.

3.1 EUSART_E301 — PRS Transmit Unavailable in Synchronous Secondary Mode

Description of Errata
When the EUSART is configured for synchronous secondary operation, the transmit output (MISO) is not driven if the signal is routed to a pin using the PRS producer (e.g., SOURCESEL = 0x13 and SIGSEL = 0x4 for EUSART0).
Affected Conditions / Impacts
Systems cannot operate the EUSART in synchronous secondary mode if the PRS is used to route the transmit output to the RX (MISO) pin. Operation is not affected in main mode when the transmit output is routed to the TX (MOSI) pin using the PRS producer nor is operation affected in any mode when the GPIO_EUSARTn_RXROUTE and GPIO_EUSARTn_TXROUTE registers are used.
Workaround
There is currently no workaround for this issue.
Resolution
This issue is resolved on revision B devices.

3.2 I2C_E303 – I²C Fails to Indicate New Incoming Data

Description of Errata
A race condition exists in which the I ² C fails to indicate reception of new data when both user software attempts to read data from and the I ² C hardware attempts to write data to the I2C_RXFIFO in the same cycle.
Affected Conditions / Impacts
When this race condition occurs, the RXFIFO enters an invalid state in which both I2C_STATUS_RXDATAV = 0 and I2C_STATUS_RXFULL = 1. This causes the I ² C to discard new incoming data bytes because RXFULL = 1 and would otherwise prevent user software from reading last byte written by the I ² C hardware to RXFIFO because RXDATAV = 0.
Workaround
User software can recognize and clear this invalid RXDATAV = 0 and RXFULL = 1 condition by performing a dummy read of the RXFIFO (I2C_RXDATA). This restores the expected RXDATAV = 1 and RXFULL = 0 condition. The dummy read also sets the RXUFIF flag bit, which should be ignored and cleared. The data from this read can be discarded, and user software can now read the last byte written by the I ² C hardware to the RXFIFO (the byte which caused the invalid RXDATAV = 0 and RXFULL = 1 condition).
No data will be lost as long as user software completes this recovery procedure (performing the dummy read and then reading the remaining valid byte in the RXFIFO) before the I ² C hardware receives the next incoming data byte.
Resolution
This issue is resolved on revision B devices.

3.3 USART_E301 — Possible Data Transmission on Wrong Edge in Synchronous Mode

Description of Errata
<p>The first bit of the new data word is incorrectly transmitted on the leading clock edge of the subsequent data bit and not the trailing clock edge of the current data bit if the USART is configured to operate in synchronous mode with</p> <ol style="list-style-type: none"> 1. USART_CLKDIV_DIV = 0 (clock = $f_{HPPERCLK} \div 2$), 2. USART_CTRL_CLKPHA = 0, 3. USART_TIMING_CSHOLD = 1 and 4. Data is loaded into the transmit FIFO (say, by the LDMA) at the exact same time as the USART state machine begins to insert the requested one bit time extension of the chip select hold time (USART_TIMING_CSHOLD = 1).
Affected Conditions / Impacts
<p>Reception of each data bit by the secondary is tied to a specific clock edge. Therefore, the late transmission by the main of the first bit of a word may cause the secondary to receive the incorrect data, especially if the data setup time for the secondary approaches or exceeds one half the shift clock period.</p>
Workaround
<p>Because there is no way to specifically time a write to the transmit FIFO such that it does not occur when the USART state machine changes state, use one of the following workarounds to avoid the risk for data corruption described above:</p> <ul style="list-style-type: none"> • Set USART_CLK_DIV > 0. • Use USART_TIMING_CSHOLD = 0 or USART_TIMING_CSHOLD > 1. • Use USART_CTRL_CLKPHA = 1. This option is particularly useful with SPI flash memories as many support operation in both the CLKPOL = CLKPHA = 0 and CLKPOL = CLKPHA = 1 modes.
Resolution
<p>This issue is resolved on revision B devices.</p>

3.4 USART_E302 — Additional SCLK Pulses Can Be Generated in USART Synchronous Mode

Description of Errata
<p>When inter-character spacing is enabled (USART_TIMING_ICS > 0) and USART_CTRL_CLKPHA = 1 in synchronous main mode, an extra clock pulse is generated after each frame transmitted except the last (that frame which when sent results in both the transmit FIFO and transmit shift register being empty).</p>
Affected Conditions / Impacts
<p>The extra clock pulse generated at the end of the first frame would cause a secondary device to clock in the first bit of the next frame it expects to receive even though the USART is not yet driving that data. The secondary would lose synchronization with the main and erroneously receive all frames after the first.</p>
Workaround
<p>Do not enable inter-character spacing when CLKPHA = 1. If a delay between frames is necessary, insert one manually with a software delay loop. Data cannot be transmitted using DMA in this case.</p>
Resolution
<p>This issue is resolved on revision B devices.</p>

4. Revision History

Revision 0.5

December, 2021

- Added [RADIO_E306](#).
- Updated the resolution of [USART_E304](#).
- Replaced select terms with inclusive lexicon.

Revision 0.4

September, 2021

- Added [CUR_E302](#) and [DCDC_E302](#).
- Clarified the revision history.

Revision 0.3

June, 2021

- Updated latest device revision to revision B.
- Added [EMU_E305](#).
- Resolved [EUSART_E301](#), [I2C_E303](#), [USART_E301](#), [USART_E302](#) and [USART_E304](#).

Revision 0.2

January, 2021

- Updated the workaround in [I2C_E303](#).

Revision 0.1

September, 2020

- Initial release.

Simplicity Studio


One-click access to MCU and wireless tools, documentation, software, source code libraries & more. Available for Windows, Mac and Linux!



IoT Portfolio
www.silabs.com/IoT



SW/HW
www.silabs.com/simplicity



Quality
www.silabs.com/quality



Support & Community
www.silabs.com/community

Disclaimer

Silicon Labs intends to provide customers with the latest, accurate, and in-depth documentation of all peripherals and modules available for system and software implementers using or intending to use the Silicon Labs products. Characterization data, available modules and peripherals, memory sizes and memory addresses refer to each specific device, and "Typical" parameters provided can and do vary in different applications. Application examples described herein are for illustrative purposes only. Silicon Labs reserves the right to make changes without further notice to the product information, specifications, and descriptions herein, and does not give warranties as to the accuracy or completeness of the included information. Without prior notification, Silicon Labs may update product firmware during the manufacturing process for security or reliability reasons. Such changes will not alter the specifications or the performance of the product. Silicon Labs shall have no liability for the consequences of use of the information supplied in this document. This document does not imply or expressly grant any license to design or fabricate any integrated circuits. The products are not designed or authorized to be used within any FDA Class III devices, applications for which FDA premarket approval is required or Life Support Systems without the specific written consent of Silicon Labs. A "Life Support System" is any product or system intended to support or sustain life and/or health, which, if it fails, can be reasonably expected to result in significant personal injury or death. Silicon Labs products are not designed or authorized for military applications. Silicon Labs products shall under no circumstances be used in weapons of mass destruction including (but not limited to) nuclear, biological or chemical weapons, or missiles capable of delivering such weapons. Silicon Labs disclaims all express and implied warranties and shall not be responsible or liable for any injuries or damages related to use of a Silicon Labs product in such unauthorized applications.

Note: This content may contain offensive terminology that is now obsolete. Silicon Labs is replacing these terms with inclusive language wherever possible. For more information, visit www.silabs.com/about-us/inclusive-lexicon-project

Trademark Information

Silicon Laboratories Inc.[®], Silicon Laboratories[®], Silicon Labs[®], SiLabs[®] and the Silicon Labs logo[®], Bluegiga[®], Bluegiga Logo[®], EFM[®], EFM32[®], EFR, Ember[®], Energy Micro, Energy Micro logo and combinations thereof, "the world's most energy friendly microcontrollers", Redpine Signals[®], WiSeConnect, n-Link, ThreadArch[®], EZLink[®], EZRadio[®], EZRadioPRO[®], Gecko[®], Gecko OS, Gecko OS Studio, Precision32[®], Simplicity Studio[®], Telegesis, the Telegesis Logo[®], USBXpress[®], Zentri, the Zentri logo and Zentri DMS, Z-Wave[®], and others are trademarks or registered trademarks of Silicon Labs. ARM, CORTEX, Cortex-M3 and THUMB are trademarks or registered trademarks of ARM Holdings. Keil is a registered trademark of ARM Limited. Wi-Fi is a registered trademark of the Wi-Fi Alliance. All other products or brand names mentioned herein are trademarks of their respective holders.



Silicon Laboratories Inc.
400 West Cesar Chavez
Austin, TX 78701
USA

www.silabs.com